

Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number.

(Also Form PTO-1050).

UNITED STATES PATENT AND TRADEMARK OFFICE  
CERTIFICATE OF CORRECTION

PATENT NO.: 6,962,639 *B2*

Page 1 of 1

APPLICATION NO.: 10/619,350

ISSUE DATE: November 8, 2005

INVENTOR(S) Takehito Ito, Toshiaki Aragane, Koji Kitahama and Syunichi Imahigashi

It is certified that an error appears or errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 11, line 54 should read as follows:

*NO* [ "pad is at a side surface on the cog ~~rest~~ and b) a free end of" ]

RECEIVED-USPTO  
Patent Examination

MAILING ADDRESS OF SENDER: (Please do not use customer number below):

AUG 29 2008

Wood, Phillips, Katz, Clark & Mortimer  
Citigroup Center, Suite 3800  
500 West Madison Street  
Chicago, Illinois 60661-2562  
(312) 876-1800 (phone)

This collection of information is required by 37 CFR 1.322, 1.323, and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process an application. Confidentiality is governed by 35 U.S.C. 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hour to complete, including gathering, preparing, and submitting the completed application form to the USPTO. Till will vary depending upon the individual case. Any comments on the amount of time you require to complete this form and/or suggestions for reducing this burden, should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, U.S. Department of Commerce, P.O. Box 1450, Alexandria, VA 22313-1450. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: ATTENTION CERTIFICATE OF CORRECTIONS BRANCH, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.



UNITED STATES PATENT AND TRADEMARK OFFICE

Commissioner for Patents  
United States Patent and Trademark Office  
P.O. Box 1450  
Alexandria, VA 22313-1450  
[www.uspto.gov](http://www.uspto.gov)

Date Mailed : September 16, 2008

Patent No. : 6,962,639 B2

Inventor : Ito et al

Patent Issued : November 8, 2005

Title : POWER TRANSMISSION BELT AND A METHOD OF FORMING  
A POWER TRANSMISSION BELT

Docket No. : 00650-0742US

Re: Request for Certificate of Correction

Consideration has been given your request for the issuance of a certificate of correction for the above-identified patent under the provisions of Rule 1.322.

Inspection of the file of the application for the patent reveals that column 11, line 54 of the specification is/are printed in accordance with the record in the Patent and Trademark Office, as passed to issue by the examiner. Therefore, no correction is in order here under Rule 1.322 or 1.323.

In view of the foregoing, your request for certificate of correction is hereby denied. However, further consideration will be given these matters, upon receipt of a request for certificate of correction under the provisions of 1.323, accompanied by the appropriate fee which is presently \$100.

Future correspondence concerning this matter should be filed and directed to Decisions & Certificates of Correction Branch.

Commissioner of Patents  
P.O. Box 1450  
Alexandria, VA 22313-1450  
Attn: Certificates of Correction Branch

David Irvine  
Cecilia Newman, Supervisor  
Decisions & Certificates of Correction Branch  
703/308-9590 or 703/305-4362 (Fax 571/270-9806)

John S. Mortimer  
Wood Phillips Katz Clark & Mortimer  
Citicorp Center – Suite 3800  
500 West Madison Street  
Chicago, Il. 60661-2562

MJD/ di